## ROAD SAFETY EVALUATION ON JENDRAL SUDIRMAN ROAD IN KUPANG CITY ( VISUAL INVESTIGATION )

Final Project Report

#### Made by:

#### VANNY ALFIANI YOSEFA BERE LAKA

STUDENT ID: 15 13 16188



# INTERNATIONAL CIVIL ENGINEERING PROGRAM FACULTY OF ENGINEERING UNIVERSITAS ATMA JAYA YOGYAKARTA YOGYAKARTA

2021

### STATEMENT

I signed below stating that the final project with the title:

# "ROAD SAFETY EVALUATION ON JENDERAL SUDIRMAN ROAD IN KUPANG CITY (VISUAL INVESTIGATION)"

It is the result of my own work and not a result of of plagiarism of other people's work. Ideas, research data, and quotes directly or directly derived from the writings or ideas of other expressly provided in this Final Project. If it is proven later that this Final Project is the result of plagiarism, the graduation certificate that I received will be canceled and returned to Universitas Atma Jaya Yogyakarta.

Yogyakarta, March 6<sup>th</sup> 2021

Whatmada the remarks,

Vanny Amani Tusera bere Laka

6AHF912258722

#### **APPROVAL**

#### Final Project Report

# ROAD SAFETY EVALUATION ON JENDERAL SUDIRMAN ROAD IN KUPANG CITY ( VISUAL INSVESTIGATION )

Made by:

Vanny Alfiani Yosefa Bere Laka

Student ID Number: 15 13 16188

has been corrected and agreed by

Yogyakarta, .....

Supervisor

Lulie Y., Ir., MT

Approved by:

Department of Civil Engineering


Chairman

FAKULTAS TEKNIK Ir. A. Y. Harijanto Setiawan, M.Eng., P.hD

#### **APPROVAL**

#### Final Project Report

# ROAD SAFETY EVALUATION ON JENDRAL SUDIRMAN ROAD IN KUPANG CITY ( VISUAL INVESTIGATION )



has been examined and approved by the examination committee

Supervisor

Signature /

Date

Chairman

: Lulie Y., Ir., MT.

Secretary

: Dr. Ir. J. Dwijoko Ansusanto, M.T.

Member

: Dinar Gumilang Jati, ST., M.Eng


5-3-2021

#### **PREFACE**

First of all, the author would like to thank Jesus for all His blessings that the author could finish this final project report. Final project is a requirement to obtain bachelor's degree for students of Universitas Atma Jaya Yogyakarta. For the completion of this final project, the author would like to express her gratitude towards:

- 1. Lulie Y., Ir., MT as the final project supervisor who had guided the author during the processing of this report.
- Dr. Eng. Luky Handoko, ST., M.Eng. as the dean of Engineering Department in Universitas Atma Jaya Yogyakarta.
- 3. DR. Ir. Imam Basuki, M.T. as the head of Civil Engineering Department in Universitas Atma Jaya Yogyakarta.
- 4. Johan Ardianto, S.T., M.Eng., as the coordinator of International Civil Engineering Program in Universitas Atma Jaya Yogyakarta.
- 5. All the lectures in the civil engineering department, especially in International Civil Engineering Program.
- 6. The author's family members for their support and prayers that helped the author to finish the final project report.
- 7. All the students from International Civil Engineering Program, especially from batch 2015, who helped the author during his study period.
- 8. All parties that cannot be mentioned one by one, thank you for all your support.

The author realize that this report has many mistakes and still have room for further improvement. Based on that fact, any suggestion and critics will be gladly accepted.



#### TABLE OF CONTENT

COVER PAGE	i
STATEMENT	ii
APPROVAL	iii
PREFACE	v
TABLE OF CONTENT	vi
LIST OF TABLES	xi
LIST OF FIGURES	xii
	xiv
ABSTRACT	XV
CHAPTER I: INTRODUCTION	
1.1.Background	
1.2.Statement of Problem	3
1.3.Research Scope	4
1.4.Research Objective	4
1.5.Research Location	5
CHAPTER II : LITERATURE RIV	IEW
2.1. Road Safety Inspection	8

2.2.	Road	8
	2.2.1. Traffic Lane	9
	2.2.1. Roadside	10
	2.2.3. Sidewalk	11
	2.2.4. The Median	12
	2.2.5. Side Channel	14
	2.2.6. Curb	15
	2.2.7. Guard Rail	16
	2.2.8. Sign	18
	2.2.9. Markers	21
2.3.	Road Space	25
2.4.	Road Classification	25
	2.4.1. Classificaion According to Road Function	26
	2.4.2. Classification According to Road Status	27
	2.4.3. Classification by Road Class	28
2.5.	Road Lighting Facilities	29
СН	APTER III : THEORETICAL BASIS	
3.1	Road Safety Inspection	31
3.2	Road Safety	34
3.3	Transportation System Approach	37
3.4	Highway Equipment	37

3.5	Traffic Accident	40
СН	APTER IV: RESEARCH METHODOLOGY	
4.1	Research Sites	42
4.2	Research Data	43
	4.2.1. Primary Data	43
	4.2.2. Secondary Data	43
4.3	Research Tools	43
	7	
	4.3.1. Camera Digital	44
	4.3.2. Laptop	44
		4.5
	4.3.3. Tape Rollers	45
	4.3.4. Inspection Form	45
	4.3.5. Android Application	48
1 1	December Com-	48
4.4	Research Steps	48
4.5.	. Research Data Analysis	49
	Research Flowchart	
СН	IAPTER V: ANALYSIS AND DISCUSSION	
5.1	General Description Of the Research Location	51
5.2	Population Data	52
5.3	Accident Data	53

5.3.1. Traffic Accident Data Based on Victim Type5.	3
5.3.2. Traffic Accident by Vehicle Type5.	3
5.4 Inspection Station Mapping54	4
CHAPTER VI: CONCLUSION AND SUGGESTION	
6.1 Conclusion	6
6.1.1. Problem on Jendral Sudirman Road70	6
6.1.2. Handling Problems on Jendral Sudirman road in Kupang City7	7
6.2 Suggestion7	7
REFERENCES 7	8
APPENDICES	
1. Formuir Audit Keselamatan Jalan 0 + 500 (Indonesian Version) 80	0
2. Formuir Audit Keselamatan Jalan 1 + 000 (Indonesian Version)90	0
3. Formuir Audit Keselamatan Jalan 1 + 500 (Indonesian Version)10	0

#### LIST OF TABLES

Table 1.1 Accident Data on Jalan Jendral Sudirman, Kupang City	2
Table 2.1 Minimum Median Width	13
Table 2.2 Placement of Street Lighting Lamps	30
Table 3.1 List of Checks in Road operational understanding	32
Table 3.2 Responsible for Five Safe Pillars	36
Table 4.1 Road Operational Stage Inspection Form	46
Table 5.1 Number of Population in Kupang Regency in 2014-2017	52
Table 5.2 Number of Traffic Accidents by Type of Victim on Jendral Sudirman Street	53
Table 5.3 Number of Traffic Accidents by Vehicle Type on Jendral Sudirman Street	54

#### LIST OF FIGURES

Figure 1.1 Map of East Nusa Tenggara Province		5
Figure 1.2 Jendral Sudirman road, Kupang City		6
Figure 1.3 Research location on Jendral sudirr	nan road, Kupang City (1)	6
Figure 1.4 Research location on Jendral sudirr	nan road, Kupang City (2)	7
Figure 2.1 Roadside Details		11
Figure 2.2 Sidewalk Details		12
Figure 2.2 Sidewalk Details  Figure 2.3 Median Details	1JAKA K	14
Figure 2.4 Side Channel Details		
Figure 2.5 Curbs Details	1 / \ 7 /	16
Figure 2.6 Guard Rails Details		18
Figure 2.7 Warning Sign		19
Figure 2.8 Ban Sign		19
Figure 2.9 Command Sign		20
Figure 2.10 Signposts		20
Figure 2.11 Types of Longitudinal markers		21
Figure 2.12 Types of Transverse markers		22
Figure 2.13 Types of oblique markers		22
Figure 2.14 Type of symbol markers		23
Figure 2.15 Type of yellow square markers		23
Figure 2.16 Lane markings		24
Figure 2.17 Lane		24
Figure 2.18 Types of traffic island		25
Figure 4.1 Map of Jendral Sudirman Road in	Kupang City	42
Figure 4.2 Digital Camera		44
Figure 4.3 Laptop		44
Figure 4.4 Tape Rollers		45

48
51
54
55
56
57
58
59
61
62
63
64
65
66
69
70
71
72
73

#### LIST OF APPENDICES

Appendix 1. Formuir Audit Keselamatan Jalan 0 + 500 (Indonesian Version)

Appendix 2. Formuir Audit Keselamatan Jalan 1 + 000 (Indonesian Version)

Appendix 3. Formuir Audit Keselamatan Jalan 1 + 500 (Indonesian Version)



#### ABSTRACT

### ROAD SAFETY EVALUATION ON JENDRAL SUDIRMAN ROAD IN KUPANG CITY (VISUAL INSVESTIGATION)

**KUPANG CITY**, Vanny Alfiani Yosefa Bere Laka, Student ID Number 15.13.16188, year 2019, Transportation Engineering, International Civil Engineering Program, Department of Civil Engineering, Faculty of Engineering, Universitas Atma Jaya Yogyakarta.

Based on the data from the East Nusa Tenggara Regional Police, Kupang Resort there were 13 traffic accidents in 2015, then increased to 29 traffic accidents in 2016 and in 2017 to 31 traffic accidents on Jendral Sudirman Road, Kupang city. Traffic accidents themselves are caused by several related factors such as humans, vehicles, roads and / or the environment.

The research was conducted at Jendral Sudirman Road, Kupang City which has the status of a provincial road and functions as a secondary collector road. The research data was taken by conducting an inspection along Jendral Sudirman Road. The data taken includes a decrease in road quality, placement of signs, non-functioning street lighting, road drainage, road markings and an traffic sign that will affect road safety on Jendral Sudirman Road, Kupang City.

From the results of the inspection, it was found that problems related to road complementary buildings and road facilities in the form of road markings that have begun to be erased, lack of signs and signs covered by tree branches in certain road segments, road damage such as cracks and holes in the road, entry of sand material into the road body, lack of pedestrian facilities (sidewalks and zebra crossings), lack of street lighting facilities and not optimal street lighting functions in several road segments. Based on the problems obtained from the results of the inspection, suggestions for handling problems were given to reduce hazards that could disrupt road safety on Jendral Sudirman Road, Kupang City. The suggestions given are painting the road markings, repairing the road surface, adding and repairing the traffic sign, making improvements and adding to the street lighting facilities, adding facilities for pedestrians, cleaning the sand material that enters the road and make improvements to traffic signs.

Keywords: Accidents, Inpections, Problems